Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.


 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner North 19

Corner not previously set

Set brass cap by single proportion- See C. of S No. 541 for adjacent corners.



T. 36N R. 27W PMM

corner this sheet