INSTRUCTIONS

1. Original and/or:
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

T. 360 R. 27W P.M.M. Lincoln Corner North 14 corner Sec. C

Corner not previously set

Set brass cap by single proportion. See C. of S. No 541 for adjacent corners

E N C	CERTIFICATION 1.
2989 ES 31.69 E	Signature Ground Party Claer L. D. K. Macquard certify that this Corner Record correctly represents work performent by the or under by direction in compliance with the "Corner Recordation Act" (70-22-10), et seq., M.D.A.) Signature of Surveyork Scal Date: 7-C-81 Reg. No. 2089 E.S.
SKETCH OF CORNER & ST. C.	Sec. 6
record" was filed for record on the	day of 1981
book No Leanner Leanner	ly beth Beel, licial Deputy

T. 36N R. 27W PMM

Cross Index No. 4-3