

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography lies, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

-CERTIFIED CORNER RECORDATION

Corner Sec. Cor. Sec. 10, 11, 14 & 15 T. 36N R. 27W P.M.M. Lincoln County


Record: Set a post 4' long x 4" sq. with marked
Stone 12" in the ground.

Dug pits for RMs

Remonumentation:

Found stone firmly set - set brass cap & buried
Original stone alongside.

Found BLM brass cap



SKETCH OF CORNER

CERTIFICATION

I, _____
certify the information shown herein is true and correct.

Signature Ground Party Chief

D.K. Marquardt

I, _____
certify that this Corner Record correctly represents work performed
by me or under my direction in compliance with the "Corner
Recordation Act" (70-22-101, et seq., M.D.A.)

D.K. Marquardt
Signature of Surveyor & Seal

Date: 7-10-81 Reg. No. 2282FS


Employer: _____

Office of Clerk and Recorder, County of Lincoln. This "corner
record" was filed for record on the 12th August day of 1981,
was noted on the cross-index plat and is assigned page No. 1186, in
book No. 1

Eleanor L. Vaughn, by Betty Beel,
County Official deputy

Cross Index No. J-17 T. 36N R. 27W PMM

Sec. 11



• - corner this sheet