- 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION


Corner <u>Sec. Cor 8, 9, 16 & 17</u> T. 3GN R. DTW P.M.M. Lincoln Record: Set a sandstone 20x8x6 ins. 15 ins. in the ground Dug pits for Rms.

Found Haskell brass cap.

See Cof S. No 669 for adjacent corners.

was noted on the cross-index plat and is assigned page No. 1539

book No. 🚣



Eleanor L. Chughn by County Official

J-9 T. 3GN R. 27W PMM

corner this sheet