INSTRUCTIONS

ent record used to evaluate the corner

 Original and/or si
 Description of cylde found, note discrepancies in the record, state method of corners.

- Description of monument and accessories set to perpetuate the corner position.
 Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner W. 1/16 on South Bdy. Sec. 34 T. 36 N. R. 27 W. P.M.M. Lincoln County

There is no survey of corner recordation on file for this corner.

There was no evidence of a monumented corner found.

CORNER PERPETUATION

At the corner point:

Set a 3/4" x 30" aluminum rod with a 3 1/4" diameter aluminum cap, approx. 26" in the ground, marked:




from which bearing trees:

A fir , 10 ins. in dia., bears N 290 W, 14.5 ft. dist., mkd. W 1/16 S 34 BT

A fir , 5 ins. in dia., bears N \$50 E, 38.7 ft. dist., mkd. W 1/16 S 34 BT

Set a galvanized steel_post with a survey marker decal and a property -boundary decal 3 ft. North of the aluminum cap.

Painted red bands around the bearing trees and painted the scribing. Attached bearing tree signs and attached Survey Monument Signs.



CERTIFICATION certify the information shown herein is true and correct. Signature Ground Party Chief Philip A. Helps certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the Recordation Act." (70.22388, et seq., M.D.A.)

Employer: F & H Land Surveying, Whitefish

4739 S

Declination 21° E. SKETCH OF CORNER

Sec. _ . This "corner

Office of Clerk and Recorder, County of _ Lincoln Mov. 30 day of 1987, record" was filed for record on the _ was noted on the cross-index plat and is assigned page No. ___ book No. ..

Z - 14 T. 36 N_R. 27 W PMM • - corner this sheet