
INSTRUCTIONS



INSTRUCTIONS

1. Original "Book" subsequent record used to evaluate the corner position.

2. Description of evidence found, not discrepancies in the record, state method of establishing lost or obliterated corners.

3. Description of monament and soccessories set to perpetuate the corner position.

4. Statch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and scaled by Land Surveyor registered in the State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTI	FIED C	CORNER	RECORD	ATION	
Corner N1/16 Sec. 36 T.	36N	R. 28W	P.M.M	Lincoln	County
RECORD:					
No Previous record on fi	le.				
FOUND:		,	<i>:</i>		
No evidence found.					
PERPETUATION:					
Set a standard 3½" USFS with a rock cairn, marked:	aluminum	cap on a 3	3/4" x 30" a	aluminum rod	12" in the ground,
from which:					
A 7" douglas fir bear N5	34°E, 17.	2 ft., mar)	ked N1/16 S	31 BT.	
A 10" larch bears West 2	8.0 ft.,	marked N1,	/16 S36 BT		
Painted the blazes red w Attached bearing tree tags and post with Survey Marker decal	Land Mor	nument sign	s on the be	s and "BT" p aring trees.	ainted on the back. Placed a 6' metal
(SEE DIAGRAM ON REVERSE)	1				
,					
		. •			
·		`	i, Stepher	CERTIFIC Jeske	CATION
	7 doug	a fir	certify the inform	tesses de la company de la com	and correct.
10" larch N54" N54" N54" N54" N54" N54" N54" N54"	ر سري وسري ا	,		R. Staples	JAMES R. STAPLES
Z8.0	The second	7	certify that this o	omer Record correctly repre ny direction in compliance w	eents with performed 9958 LS with the *Corner
		N	Lann		To the state of th
			OV .	of Surveyor & Scal / // Rcg. No. 9958	
SKETCH OF CO	RNER		·	R.S. Surveying, Inc.	
		0.	0		Sec. 36
Office of Clerk and Recorder,	County o	* Juco	he Thi	s "corner	
record" was filed for record o		CT 13, 1	994	· · · · · · · · · · · · · · · · · · ·	
was noted on the cross-index p	plat and	is assigned	d page No.	5950 in	,
book No.	Co	101/1//	ounty Office	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
•					

Cross Index No. W-25 T. 36N

NE Cor S36 FND.- Brass cap/i.p. Set N'/16 8892 NORTH (GLO) 40 chs. "/16 by accepted single proportion method. E'14 S36 FND.-Brass cap/i.p.