
CERTIFIED CORNER RECORDATION

Corner W.C. W 1/16 Sec. 24&25 T. 36N R. 27W P.M., MT Lincoln County


- I. 1975 Certificate of Survey No. 152 by D. K. Marquardt, 2989ES: For the W 1/16 cor. of secs. 24&25 set by survey, a USFS brass cap, on a 3/4 in. diam. x 20 ins. long iron pipe.
- II. Lost corner, due to flood action on the Tobacco River.
- III. Set by survey, a 3/4 in. diam. x 30 ins. long, aluminum rod, 27 ins. in the ground, with a 3 1/4 in. diam. aluminum cap mkd. as shown.



Established two bearing trees and set one steel guard post:

A spruce, 16 ins. diam., bears S33°E, 60.6 ft. dist., mkd. "WC W1/16 S25 BT". A spruce, 10 ins. diam., bears S05°W, 60.6 ft. dist., mkd. "WC W1/16 S25 BT". A 6 ft. steel guard post, East, on property line, 3.0 ft. dist. from the monument.

No bearing trees available, within limits, in sec. 24.
Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.
Attached Land Survey Monument and Property Boundary decals to the post.



County Official

corner this sheet