
## CERTIFIED CORNER RECORDATION

Corner COE 3402-1-1 Sec 11 T. 36N R. 28W P.M.M. Lincoln County


- 1. Libby Dam Lake Kookanusa Cadastrol 1972 map
- 2. Found 3" Corps of Engineers Brass Cap in 4" concrete stamped as shown.
- 3. Painted red bands around BTs and attached LSM and BT signs.


## Established:

A 10 ins. Douglas Fir bears S61°W, 14.2 ft. distant, scribed "3402—1—1 BT" A 15 ins. Douglas Fir bears N25°W, 23.3 ft. distant, scribed "3402—1—1 BT" Steel posts with PB & LSM decals, bear North & Southwest, 2.0 ft. distant.



MAGNETIC DECLINATION - 16' EAST





## SKETCH OF CORNER

Sec. 11

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors