CEDITIFIED		RECORDATION
	LURINER	_ KEL.()KI)AII()IV

Corner COE 2905-1 Sec22 T. 36N R. 28W P.M.M. Lincoln County


- 1. Libby Dam Lake Kookanusa Cadastral 1972 map
- 2. Found:

A $3\frac{1}{4}$ " USFS Aluminum Cap on 3/4" Alum. Rod, stamped as shown. (2905–1) A $3\frac{1}{4}$ " USFS Aluminum Cap on 3/4" Alum. Rod, stamped as shown. (W1/16 CC) bears N19*26'W, 3.58 ft. of COE 2905–1.


3. Painted red bands around BTs and attached LSM and BT signs.

Established:

An 8 ins. Douglas Fir bears S11°E, 37.3 ft. distant, scribed "2905—1 BT" A 9 ins. Douglas Fir bears S71°W, 26.6 ft. distant, scribed "2905—1 BT" Steel post with PB & LSM sign bears North, 2.0 ft. distant.



MAGNETIC DECLINATION - 16' EAST



corner this sheet