- gent record used to evaluate the corner position
- 2. Description of evis ound, note discrepancies in the record, state method of estal.

Description of monument and accessories set to perpetuate the corner position.

- Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
  Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION


T. 36N R. 27W/28W P.M.M. Corner <u>N-1/1</u>6 Lincoln \_County

- I. None
- II. None
- Drove a 3/4" x 24" rod into ground with 3-1/4" alum.  $III_{\bullet,}$ cap for corner position.

Established BT's as follows: 5" fir bears S.62°E., 2.5', scribed N-1/16 S19 BT 7" fir bears S.55°W., 12.5', scribed N-1/16 S24 BT

Posted BT, Attention, and Land Monument signs; painted blazes red; drove steel post in ground along side of corner monument.

For monument location, see the Certificate of Survey on file.



7 FIR

SKETCH OF CORNER

CERTIFICATIÓN

certify the information shown herein is true and correct.

Signature Ground Party Chief

Gene Warren

certify that this Corner Record correctly represents werk performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

Warren

11-85 Reg. No.

Employer: ROCKY MOUNTAIN SURVEYORS

24 Sec. Office of Clerk and Recorder, County of \_ \_\_ . This "corner Dec record" was filed for record on the \_ was noted on the cross-index plat and is assigned page No. 3201 book No.

Cross Index No. 025 T. 36N R. 28W PMM

corner this sheet