## INSTRUCTIONS

ait record used to evaluate the corner position, ound, note discrepancies in the record, state method of estab. Original and/or sut
 Description of evid corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography thes, position of accessories, etc.

5. Certification must be signed and scaled by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

NE-1/16Sec. 23 T. 36N R. 28W Corner . P.M.M. \_\_\_ Lincoln County

## I. None


- Found 1" pipe with brass disc stamped "E.S. 2989", II. set D.K. Marquardt, per Certificate of Survey No. 118.
- III. Drove a 3/4" x 24" rod into ground with 3-1/4" alum. cap for true corner position.


1"-pipe-with brass disc bears S.32°23'E., 0.72'

Established BT's as follows: 6" fir bears S.67°E., 21.9', scribed NE-1/16 S23 BT 13" fir bears S.15°W., 3.0', scribed NE-1/16 S23 BT

Posted BT, Attention, and Land Monument signs; painted blazes red; drove steel post in ground along side corner monument.

For monument location, see the Certificate of Survey on file.





Office of Clerk and Recorder, County of Lincoh \_ . This "corner record" was filed for record on the Lic 27. ـ day of 19**5**ح was noted on the cross-index plat and is assigned page No. 3204 book No. . Cross Index No. 020 T. 36N R. 28W PMM · corner this sheet