INSTRUCTIONS

- nt record used to evaluate the corner position.
- 1. Original and/or sul 2. Description of evic bund, note discrepancies in the record, state method of estab corners

Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch or corner, show all perthent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION


T. 36N CS-1/16 Sec. 23 28W Corner_ Lincoln _County

- None
- II. None
- Drove a 3/4" x 24" rod into ground with 3-1/4" alum. III. cap for corner position.

Established BT's as follows: 11" pine bears S.6°E., 35.4', scribed CS-1/16 S23 BT 9" pine bears N.25°W., 42.7', scribed CS-1/16 S23 BT

Posted BT, Attention, and Land Monument signs; painted blazes red; drove steel post in ground along side corner monument.

For monument location, see the Certificate of Survey on file.



• - corner this sheet

9" PINE A	CERTIFICATION
E. T.S.	certity the information shown herein is true and correct. Signature Ground Party Chief I. H. Gene Warren
3.6° E. 2 35.4' 11" PILLE BT	certify that this Corner Record correctly represents work performed by nie or under by direction in compliance with the "Corner. Recordation Act" (70-22-10), et seq., M.D.A.) Hung Wanner Signature of Surveyor & Seal Date: 11-85 Reg. No. 27348
SKETCH OF CORNER	Employer: ROCKY MOUNTAIN SURVEYORS
Office of Clerk and Recorder, County of <u>Lincoln</u> record" was filed for record on the <u>Dic 27</u>	This "corner Sec. 23 day of 1925
was noted on the cross-index plat and is assigned page No book No for the Sugar County of the county of the cross-index plat and is assigned page No	

Cross Index No. Q19 T. Z6N R. Z8W PMM