## INSTRUCTIONS

1. Original and/or sub 2. Description of evid nt record used to evaluate the corner position. ound, note discrepancies in the record, state method of estab corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography thes, position of accessories, etc.

5. Certification must be signed and scaled by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

CW-1/16 Sec. 23 T. 36N R. 28W P.M.M. Lincoln Corner\_

> I. None


II. None


Drove a 3/4" x 24" rod into ground with 3-1/4" alum. III. cap for corner position.

Established BT's as follows: 5" fir bears S.23°E., 9.2', scribed CW-1/16 S23 BT 7" fir bears N.15°W., 12.6', scribed CW-1/16 S23 BT

Posted BT, Attention, and Land Mounument signs; painted blazes red; drove steel post in ground along side corner monument.

For monument location, see the Certificate of Survey on file.





Cross Index No. P18 T. 36N II. 28W PMM

by me or under by direction in compliant Recordation Act" (70-22-101, et seq., M.D.A.) Gene Warren Reg. No. 27345 Employer \_\_\_ ROCKY MOUNTAIN SURVEYORS . This "corner day of 19**%** 

Office of Clerk and Recorder, County of Dec 27 record" was filed for record on the \_\_\_ was noted on the cross-index plat and is assigned page No. book No. .

· - corner this sheet