

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION


HES 1131 COR 11 SEC 7 T36N R31W LINCOLN Co.

FND OLD STONE MON W/ "X" CUT 1.0' ABOVE
GRD & "11 HES 1131" WRITTEN ON
SE SIDE

FND OLD BT 15" SPRUCE S48°W 31.80' DIST
OLD SIGN READS: N43°E 31.8' 12/82

FND OLD BT 14" SPRUCE S05°W 38.60' DIST
OLD SIGN READS: N04°E 38.5' 12/82

SET STEEL POSTS W/ DECALS 54-2 & 54-9
1) WEST 1.5' DIST
2) SOUTH 1.1' DIST



SKETCH OF CORNER

CERTIFICATION

I, _____
certify the information shown herein is true and correct.

Signature Ground Party Chief

1. THOMAS E. SANDS

I certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

Signature of Surveyor & Seal

Date: 7/23/93 Reg. No. 2975-S


Employer: SANDS SURVEYING, INC.

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the July 27, 1993 day of 19, was noted on the cross-index plat and is assigned page No. 5353, in book No. _____

Coral M. Cummings By DB
County Official

Cross Index No. HES1131-11 T. 36N R. 31W PMM

Sec.



• - corner this sheet