- Description of monument and accessories set to perpetuate the corner position.
 Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking topography ties, position of accessories, etc.
- Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

HES 484 CORI SECG T3GN R3IW LINCOLN CO.

FNO OLD STONE MON W/ X" CUT 0.5' ABOVE GRD & "I HES 484" WRITTEN ON NW SIDE

SET BT (Z" SPRUCE NORTH & 30' DIST SCRIBED X BT"

SET BT IS" SPRUCE NOWE 18.48' DIST SCRIBED "I HES 484"

SET STEEL POSTS W/ DECAUS 52-4 \$ 52-9

1) NIIOE 1.70 DIST

Z) SSOOW Z.O' DIST

/	(8/5BT)
4	DBT
	STONE

SKETCH OF CORNER

CEDTI	em	٠,	*11	

certify the information shown herein is true and correct.

Signature Ground Party Chief

Thomas E. Sands

certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act," (70-22-101, et seq., M.D.A.)

7/23/93 Reg. No. 7975-S
Sands Surveying, Inc.

Office of Clerk and Recorder, County of 27, 1993 day of 19, record" was filed for record on the . was noted on the cross-index plat and is assigned page No County Official book No.

Cross Index No. HES 484-1 T. 36N/R. 31W PMM

