d accessories set to perpetuate the corner position

Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

HES 484 COR 2 SEC 6 T36N R3/W LINCOLN CO.

FNO SPIKE IN WATER

FNO SPIKE ON PROPERTYLINE 98.00 FEET FROM COR Z TO COR T OF HES 484

FNO CORT HES 484 STONE MON W/ "X" CUT 1118.89" VA TO CORZ.

FNO CORS HES 484 STONE MON W/"X" CUT 651.16' 0/A TO COR. 2.

JET WC ON PROPERTY CINE (CORG - CORT) 38.60' FROM COR 2

SET WC. ON PROPERTY LINE (CORG + CORS) 72.02' FROM COR2

SET STEEL POSTS W/ DECALS. 52-4 \$ 52-9 DN 50.30'E 0.51' DIST.

2) S89.Z4'Z7'E 0.75' DIST

4ES 484

SKETCH OF CORNER

CERTIFICATION

certify the information shown herein is true and correct.

Signature Ground Party Chief

Thomas E. Sands

certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the Recordation Act 770-22-101, et seq., M.D.A.;

7/23/93 Reg. No. Employer: Sands Surveying, Inc.

Office of Clerk and Recorder, County of _ . This "corner record" was filed for record on the _ day of 19 .

was noted on the cross-index plat and is assigned page No. County Official book No.

Cross Index No HES 484-2 T36N R. 3/W PMM