

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

• CERTIFIED CORNER RECORDATION


Corner South 1/4 corner Sec. 32 T. 37N R. 27W P.M.M. Lincoln County

Record:

Set a limestone 18x12x6" in the ground from which:
 a pine 36" diameter bears S. 10°30' E. 126 lks
 a pine 14" diameter bears N. 120° W. 30 feet

Nothing found - set brass cap by single proportion

See C. of S. No. 541 for adjacent corners



SKETCH OF CORNER

CERTIFICATION

I, _____
 certify the information shown herein is true and correct.

Signature Ground Party Chief

I, D.K. Marquardt
 certify that this Corner Record correctly represents work performed
 by me or under by direction in compliance with the "Corner
 Recordation Act" (70-22-101, et seq., M.D.A.)

D.K. Marquardt
 Signature of Surveyor & Seal

Date: 7-6-81 Reg. No. 2989ES


Employer: _____

Office of Clerk and Recorder, County of Lincoln. This "corner
 record" was filed for record on the 17th July day of 1981,
 was noted on the cross-index plat and is assigned page No. 1160, in
 book No. 1

Thomas L. Vaughn, by Betty Beal,
 County Official Deputy

Cross Index No. 2-7 T. 37N R. 27W P.M.M.

Sec. 32



● - corner this sheet