3. Description of monument and accessories set to perpetuate the corner position.

- Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner 4 corner between Sec. 32 & 33 T. 37N R. 27W P.M.M. Lincoln

Record

Set a limestone 12 x 11 x 10 ins. Bins in the ground marked 14. on West face

Dug Pits N&S of Stone

No evidence found

Set brass cap at the intersection of the stone fences.

See Cof 5. No. 541 for adjacent corners.

CERTIFICATION certify the information shown herein is true and correct. D.K. Marguardt (70-22-101, et seq., M.D.A.) Ella Guard Signature of Surveyor & Sca Date: 7-681 Reg. No. <u>3989E</u>S **SKETCH OF CORNER**

Office of Clerk and Recorder, County of _ . This "corner record" was filed for record on the was noted on the cross-index plat and is assigned page No. County Official . т. <u>ЭТ Ю</u> R. <u>ЭТ Ы</u> РММ

corner this sheet