
INSTRUCTIONS

nt record used to evaluate the corner position



4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ites, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana,

6. Fill in-Cross Index & Seciton Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION


Corner SE cor. Sec. 34-5W cor. Sec. 35 T. 3710 R. 27W P.M.M. Lincoln

Record:

Set a sandstone 12 x 12 x 5" 8" in the ground for standard corner with a notches on East & 4 notches on west faces

Dug pits NE & W of stone

No evidence found- Set brass cap by single proportion between SW sec. cor & c.c. stone. See C. of S. No. 541 for adjacent corners.



was noted on the cross-index plat and is assigned page No. _ County Official 2-17 T. 37 NR 27W PMM

corner this sheet