INSTRUCTIONS

2. Description of evidence found, note discrepancies in the record, state method of establi

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner 4 corner between 534 235 T. 37N R. 27W P.M.M. Lincoln


Record.

Set a limestone 14 × 10×4" 10" in the ground for 14 sec. cor. marked 14 on West face

Dug Pits N& Sof Stone

No evidence found- Set brass cap at intersection of fenceline & & of County Road.

See C. of S. No. 541 for adjacent corners.



Cross Index No. X-17 T. 3710 R274 PMM

corner this sheet