## INSTRUCTIONS

- Original and/or sub Description of

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

*S 27* 

S 26

SET NAIL NORTH SIDE OF FX POST

## **CERTIFIED CORNER RECORDATION**

