
CERTIFIED CORNER RECORDATION

Corner	C.O.E.	Sec.	20	T.	37N	R.	27W	P.M., MT	Lincoln	County
	5606/2									

I. <u>1970 Corp. of Engineers Libby Dam Lake Koocanusa Cadastral District file No. E 53-1-154:</u> For corner no. 2 of tract 5606, set a standard U.S.C.E. disk, mkd. as shown:



II. Found a 3 1/2 in. diam., Corps of Engineers brass cap, in concrete, tipped on side, in creek bed, at fence corner. Righted monument in old position and rocked in place, cap mkd. as shown.

from which:


An old steel fence post, bears S30°E, 0.7 ft. dist., with a Property Boundary decal attached.

III. Established two bearing trees:

A fir, 17 ins. diam., bears N24°W, 45.1 ft. dist., mkd. "COE 5606/2 BT". A spruce, 9 ins. diam., bears N75°W, 36.03 ft. dist., mkd. "COE 5606/2 BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. Corner falls near Murray Springs Well Site.

Magnetic Declination: 20° East.



I. Rex O. Rice

certify the information shows hereful and careet.


I. Ronald A. Pearson
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)

Signature of Surveyor & Seal

Date: 04/30/97

Reg. No.: 9008LS

Employer: U.S. FOREST SERVICE



Cross Index No.

C.O.E 5606/2-M.S. Well Site 37N ^{R.} 27W ^{P.M., MT}