
CERTIFIED CORNER RECORDATION

Corner	C.O.E.	Sec.	20	Т.	37N	R.	27W	P.M., MT	Lincoln	County
	5606/1D									

I. 1970 Corp. of Engineers Libby Dam Lake Koocanusa Cadastral District file No. E 53-1-154: For corner no. 1D of tract 5606, set a standard U.S.C.E. disk, mkd. as shown:




- II. Found a 3 1/2 in. diam., Corps of Engineers brass cap, firmly set, protruding 2 ins. above the ground, mkd. as shown above. No bearing trees found.
- III. Established two bearing trees:

A fir, 6 ins. diam., bears S09°W, 19.1 ft. dist., mkd. "COE 5606/1D BT". A fir, 12 ins. diam., bears S35°E, 20.8 ft. dist., mkd. "COE 5606/1D BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. Corner falls near Murray Springs Well Site.

Magnetic Declination: 20° East.



	I. Rex O. Rice					
	certify the information shown herein is true and correct.					
	. Denoted & Program					
	I, Ronald A. Pearson					
	certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)					
_	Contestibility compliance with the Contest Hacordapon Act (70-22-101, 81 seq., M.C.A.)					
`						
	Valle Har					
	Signature of Surveyor & Seal					
	Date: <u>05/13/97</u>					
	····· ··· ··· ··· ··· ··· ··· ··· ···					
	Dec. No 00001 C					
	Reg. No.: 9008LS					
	s . U.O. FOREST SERVICE					
	Employer: U.S. FOREST SERVICE					

Office of Clerk and Recorder, County of _______. This "corner record" was filed for record on _______ was noted on the cross-index plat and is assigned page No.9893,

in book No. _____

CORAL M.CUMMINGS



Sec. 2	0					
			T			
			$\overline{\mathbb{L}}$			
- corner this sheet						

Cross Index No.

C.O.E. 5606/1D 37N ^{R.} 27W