
CERTIFIED CORNER RECORDATION

Corner	C.O.E.	Sec.	20	T.	37N	R.	27W	P.M., MT	Lincoln	County
	5606/1B									•

I. 1970 Corp. of Engineers Libby Dam Lake Koocanusa Cadastral District file No. E 53-1-154: For corner no. 1B of tract 5606, set a standard U.S.C.E. disk, mkd. as shown:




- II. Found a 3 1/2 in. diam., Corps of Engineers brass cap, firmly set, protruding 1 in. above the ground, mkd. as shown above. No bearing trees found.
- III. Established two bearing trees:

A cedar, 5 ins. diam., bears N50°W, 10.0 ft. dist., mkd. "X" on snowblaze "BT". A fir, 12 ins. diam., bears S21°W, 30.3 ft. dist., mkd. "COE 5606/1B BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. Corner falls near Murray Springs Well Site.

Magnetic Declination: 20° East.



I. Rex O. Rice

certify the information shown herein is true and correct.

I. Ronald A. Pearson

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Sorner Recordation Act" (70.22-101, et seq., M.C.A.)


Signature of Surveyor & Seal

Date: 05/13/97

Reg. No.: 9008LS

Employer: U.S. FOREST SERVICE

Office of Clerk and Recorder, County of ______. This "corner record" was filed for record on _____ was noted on the cross-index plat and is assigned page No. 9896, in book No. ______ CORAL M.CL'MMINGS



Cross Index No.

C.O.E. 5606/1B 37N ^{R.} 27W