
CERTIFIED CORNER RECORDATION

Corner	C.O.E.	Sec.	20	Т.	37N	R.	27W	P.M., MT	Lincoln	County
	5606/1A									

I. <u>1970 Corp. of Engineers Libby Dam Lake Koocanusa Cadastral District file No. E 53-1-154</u>: For corner no. 1A of tract 5606, set a standard U.S.C.E. disk, mkd. as shown:




- II. Found a 3 1/2 in. diam., Corps of Engineers brass cap, firmly set, protruding 3 ins. above the ground, mkd. as shown above. No bearing trees found.
- III. Established two bearing trees:

A spruce, 15 ins. diam., bears N25°W, 27.7 ft. dist., mkd. "X" on snowblaze "BT". A spruce, 11 ins. diam., bears N84°W, 17.3 ft. dist., mkd. "COE 5606/1A BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. Corner falls near Murray Springs Well Site.

Magnetic Declination: 20° East.



	I. Rex O. Rice							
	certify the information shown helein is true and correct.							
	·							
	ı, Ronald A. Pearson							
	certify that this Corner Record correctly represents week performed by me or under my							
\subset	direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.)							
\	Sand the san							
	$N \cup A \cup N \cup A \cup $							
	La L							
	Signature of Surveyor & Seal							
	Date: 05/13/97							
	Date. OS, TO, OT							
	Reg. No.: 9008LS							
	Employer: U.S. FOREST SERVICE							

Office of Clerk and Recorder, (County of This "corner record" was filed for record
onJULY 31,1997	was noted on the cross-index plat and is assigned page No. 9897 ,
in book No	CORAL M.CUMMINGS B. PUB
	County Official

Sec. 20

Cross Index No.

C.O.E. 5606/1A 37N ^{R.} 27W