
CERTIFIED CORNER RECORDATION

| Corner | C.O.E. | Sec. | 20 | T. | 37N | R. | 27W | P.M., MT | Lincoln | County |
|--------|----------|------|----|----|-----|----|-----|----------|---------|--------|
| | 3901/1-2 | | | | | | | | | • |

I. 1970 Corp. of Engineers Libby Dam Lake Koocanusa Cadastral District file No. E 53-1-154: For corner no. 2 of tract 3901-1, set a standard U.S.C.E. disk, mkd. as shown:



- II. Found a 3 1/2 in. diam., Corps of Engineers brass cap, set flush, in concrete, mkd. as shown above. No bearing trees found.
- III. Established two bearing trees and one steel post:

A pine, 9 ins. diam., bears N25°W, 5.9 ft. dist., mkd. "COE 3901/1-2 BT".

A pine, 5 ins. diam., bears N65°W, 27.2 ft. dist., mkd. "X" "BT".

A 6 ft. steel post, North, on property line, 3.0 ft. dist. from the corner.

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs. Attached Land Survey Monument and Bearing Tree decals to the post.

Magnetic Declination: 20° East. ı. Rex O. Rice i, Ronald A. Pearson Date: 06/18/97 Reg. No.: 9008LS Employer: U.S. FOREST SERVICE **SKETCH OF CORNER** Sec. 20 LINCOLN This "corner record" was filed for record Office of Clerk and Recorder, County of _ JULY 31,1997 was noted on the cross-index plat and is assigned page No. 9898, CORAL M.CUMMINGS in book No. County Official corner this sheet