CERTIFIED CORNER RECORDATION

Corner W 1/16 Sec. 2 & Canada T. 37N R. 28W P.M.M. Lincoln County

1. <u>1989 Certified Corner Recordation by H. Gene Warren MT Reg. No. 2734S:</u>
"No previous record is on file for this 1/16 corner, however I did find a bearing tree with a BT tag attached. (tag unreadable)"

Set a standard 3 1/4 inch Forest Service alum. cap on 5/8 inch rod 28 inch into the ground from which:

The found BT:

A 14 inch fir bears S10°E 25.45 ft. scribe overgrown maintained with required signs and paint.

The new BT:

A 7 inch fir bears S42°W 26.60 ft. scribed W 1/16 S2 CC BT. Set a USDA steel post 24 ft. south of corner.

- 2. Found 5/8 inch rebar with no cap with 4 inch round wooden post 1/2 ft. south.

 An 18 inch douglas fir S14°E (record S10°E) 25.45 ft. from existing nail inside center with well healed face. (also BLM BT tag by NLD 2-76)

 A 10 inch douglas fir S42°W 26.60 ft. with well healed face.


 A steel post 20 ft. south of rebar with LSM and Boundary decals. (record south 24 ft.)
- 3. Put a new USFS 3 1/4 inch aluminum cap on existing 5/8 inch rebar and surrounded it with a small mound of painted stone.

 Put aluminum nail at record distance on SW BT.

 Repainted rings and blazes on BTs and put new BT tag on SE BT with new bearing tag. (already had nail in side center)

CANADA W 1/16 S2 T37N R28W C C 9748LS 2009

MAGNETIC DECLINATION- 16' EAST



record" was filed for record o	224110 BOOK: CCR CCER'S PAGE: 11362 Pages: 1	Sec. 2
was noted on the cross-index	STATE OF MONTANA LINCOLN COUNTY RECORDED: 01/27/2010 12:32 KOI: CC&R'S	
	TAMMY D. LAUER CLERK AND RECORDER	
book No.	TO: FILED,	
	Cross Index No. A-18 T. 37N R. 28W PMM	
Adapted July 1, 1981, Mo	ntana Board of Professional Engineers & Land Surveyors	