CERTIFIED CORNER RECORDATION

Corner C E 1/16 Section 11 T. 37N R. 28W P.M.M. Lincoln County

1. <u>1989 Certified Corner Recordation by MT Reg. No. 2734S</u>: Set a standard Forest Service 3 1/4 inch alum. cap on a 5/8 inch rod 26 inches into the ground;

from which:

A 7 inch pine bears S75°E, 34.27 feet scribed C E 1/16 S11 BT. A 7 inch fir bears N16°E, 31.20 feet scribed C E 1/16 S11 BT. Set a USDA steel post 3 feet south of corner.

- 2. Found 3 1/4 inch USDA aluminum cap, 2 ins. out of ground next to fence line going north and west; steel guard post is gone.

 A 12 inch douglas fir N17°E, 31.20 ft. with a well healed face.


 An 11 inch ponderosa pine S75°E, 34.27 ft. with a well healed face.
- 3. Stacked and painted a small mound of stone around monument.
 Put aluminum nails at record distance and repainted rings and blazes on BTs.
 Put up new BT tags.
 Put a steel post with LSM and Boundary Tags 3 ft. north of corner.



MAGNETIC DECLINATION - 16' EAST


FEE: \$0.00

book No. _



Cross Index No. <u>G-20 T. 37N</u> R. <u>28W</u> PMM

Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors



corner this sheet