INSTRUCTIONS

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and scaled by Registered Land Surveyor in State of Montana
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

37N. R. 28W. P.M.M. Lincoln _County

I. No original records.

II. N/A

III. Set Driveable Alum. Mon. with Rock Cairn, (5/8"x24" Alum. Mon. w/3" cap). Scribed 2 B.T.s:

A 8" Tamarack bears S.66°E., 5.20 ft., mkd. W1/16 S23 B.T.

A 7" Tamarack bears N.18°W., 6.40 ft., mkd. W1/16 S14 B.T.

McMILLEN 4659S SURV CERTIFICATION 7" TAMARACK T37N R28W W/6 514 523 L5 46595 1983 Date:12/12/83 Reg. No. 4659-S Employer: Carl R. McMillen & Assoc. SKETCH OF CORNER Office of Clerk and Recorder, County of Lincoln _ . This "corner <u>march 215t</u> day of 1984 record" was filed for record on the was noted on the cross-index plat and is assigned page No. <u>3561</u> County Official of book No. N-18 T. 37N R. 28W PMM corner this sheet