INSTRUCTIONS

uent record used to evaluate the corner position

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

N.E. 1/16 Sec. 35 37N. R. 28W. P.M.M. Lincoln Corner_ _ T. _ County I. No original records. II. N/A

III. Set an Alum. capped Mon. with rock cairn, (21/2"x30" Alum. Mon. w/3" cap). Scribed 2 trees:

A 5" Pine bears S.71°W., 32.80 ft., marked NE1/16,S35 B.T.

A 7" Red Fir bears N.28°W., 52.50 ft., marked NE1/16 S35 B.T.



