INSTRUCTIONS

quent record used to evaluate the corner position

- Description of monument and accessories set to perpetuate the corner position.
 Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

_ T. <u>___37N •</u>___R. <u>___28W •</u>____P.M.M. __ Corner N.W.-S.E. 1/64 Sec. 35 Lincoln County I. No original records. II. N/A

III. Set a Driveable Alum. Mon. with rock cairn, (5/8"x24" Alum. Mon. w/3" cap). Scribed 2 trees:

A 5" Pine bears S.49°W., 55.55 ft., marked NW-SE1/64 S35 B.T.

A 5" Pine bears N.24°W., 56.90 ft., marked NW-SE1/64 S35 B.T.



