## INSTRUCTIONS

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

- corners.

  3. Description of monument and accessories set to perpetuate the corner position.

  4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

  5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

  6. Fill in Cross Index & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

Corner W W C-C 1/64, Sec. 24 T. 37N R. 28W P.M.M. Lincoln

No GLO corner set at this point.

WINCE MA SZA

book No.


Found Corps of Engineers, U.S. Army Project Boundary marker, a 42" square concrete monument w/ brass cap marked as noted below, at fence corner to West and North. No bearing trees.

Set bearing tree witnesses: 13" Ponderosa Pine S62<sup>0</sup>E 10.5 feet mkd. S24 1/64 / 3911/2<sup>BT</sup>signed and painted as per USFS Specs.

8" Fir S10 $^{\circ}$ W 7.1 feet mkd. S24 1/64 / 3911/2 BT, signed and painted as per USFS Specs.

Set ring of stones 3' dia around corner mon.

Set steel sign post W. of mon.



Cross Index No.

Sugar by Sur.
County Official

т. <u>37N</u> R. <u>28W</u> <sub>РММ</sub>

corner this sheet