INSTRUCTIONS

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

- 3. Description of monument and accessories set to perpetuate the corner position.
 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 6. Cartification.
- Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
 Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

T.<u>37N</u> __R.__28W Corner W W 1/64 Cor. Sec. 24 P.M.M. Lincoln

No GLO corner established at this point.

W/W 169

book No. -

Found Corps of Engineers, U.S. Army Project Boundary marker, a 42" square concrete monument w/ brass cap marked as noted below, at fence corner running West and South. No bearing trees.

Set bearing tree witnesses: 10" Tamarack N61°E 41.8 feet mkd. S13 1/64 /3911/18T signed and painted as per USFS Specs.

10" fir S33 $^{\circ}$ E 34.4 feet mkd. S24 1/64 / 3911/1 BT, signed and painted as per USFS Specs.

Set a steel sign post N. of mon.

