- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Section 26, SE1, NE1 Corner U.S. Project Boundary

T. 37N R. 28N

__P.M.M. <u>Lincoln</u>

No GLO corner established at this point.

Found Corps of Engineers, U.S. Army Project Boundary marker, a 41 square concrete monument w/ brass cap marked as noted below, at corner of NEly and SE'ly wood rail fence. No bearing trees.

Set bearing tree witness: 10" fir S29°E 87.0 feet mkd. T37N R28W S26/3914/3 BT, signed and painted as per USFS Specs.

No other trees available on USA land.

A monument as per above description mkd. 3914/4 bears N83 E 144.09 feet at fence corner.

A monument as per above description mkd. 3914/2 bears S11 E 100.09 feet at fence corner.

Set steel sign post E. of mon.

Ex Wood Rail-

sign past

set steel

Fd. Brass Capped 4/12 Sq. Conc. Mon. Mkd. 2914/3

Private

Mm.

Decl. 20°E

11.5.A.

RZBW SZ6 3914/3

3914/2 **SKETCH OF CORNER** (SEE ABOVE) CERTIFICATION

Dennis D. Findorff

Signature Ground Party Chief

Robert E. Findorff

Date 6/6/87 Reg. No.

Office of Clerk and Recorder, County of June 30, 1987 record" was filed for record on. was noted on the cross-index plat and is assigned page No. book No. ounty Official

> Cross Index No. S-T 20-21 T. 37N R. 28W PMM Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

Sec. 26, 137N, R28W

· corner this sheet