2. Description of evidence found, note discrepancies in the record, state method of establishing jost or obliterated

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking,


Certification must be signed and sealed by Hegistered Land Surveyor in State of Montana.
Fill in Cross Index & Section Diagram at bottom of sheet.


CERTIFIED CORNER RECORDATION

_P.M.M. _

- (1) No previous record or evidence
- (2) Monument and accessories set to perpetuate corner position

Set a standard 3½ inch Forest Service alum, cap on 5/8 inch rod 28 inches into the ground; from which: A 6 inch fir bears N 10 W 23.50 feet scribed W 1/16 S2 BT A 14 inch fir bears S 19 W 52.15 feet scribed W 1/16 S11 BT Ste a U.S.D.A. steel post 3 feet north of corner.





E-18

Cross Index No. ...

28W

- corner this sheet