- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

  5. Certification must be signed and scaled by Registered Land Surveyor in State of Montana.

  6. Fill in Cross index & Section Diagram at bottom of sheet.


## CERTIFIED CORNER RECORDATION

Corner NW 1/16 SECTION 28

- NO previous record or evidence
- (2) Monument and accessories set to perpetuate corner, position

Set standard 3% Forest Service alum. cap on 5/8 inch rod 18 inches into the ground with rock mound, from which:
A 9 inch fir bears N 71 E 18.60 feet scribed NW 1/16 S28 BT
A 5 inch fir bears N 84 W 11.77 feet scribed NW 1/16 S28 BT
Set a 6 foot steel post 3 feet north of corner.





T. 37n R. 28W PMM

• - corner this sheet