## INSTRUCTIONS

cord used to evaluate the corner position. Original and/or subseq.
 Description of evidence , note discrepancies in the record, state method of establishin

or obliterated

corners. 3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Seciton Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

Corner CESE 1/645 Corner Section9T. 37N R. 28W P.M.M. Licoln

book No.

1991Davis Surveying , Inc.

I set a 5/8 inch dia. x 24 inch long rebar with yellow PVC cap stamped KED 4975 S from which;

> A Douglas fir, 13 inches DBH, bears N15° W 35.3 feet from center of tree, scribed CESE 1/16 S9 BT

> A Spruce,  $10\frac{1}{2}$  inches DBH, bears S 83°W 19.5 feet from the center of the tree, scribed CESE 1/16 S9 BT

> Painted a 6 inch wide red band around BTs with BT signs on front and warning signs #54.9 on back.

| En 13" Douglas fir BT  | CERTIFICATION  |
|--|--|
| 3/m<br>2/m<br>2/m<br>0 CESE 164 COR.<br>19.5 5/8" Rebort Cap<br>101/2" Spruce Bt | t. Ken E Davis certity the information shown herein is true and correct.  John Damon, Brian Leizs, Bill Signature Ground Party Chief Reichel  Certify that this Corner Record correctly represents work performed by the of union by direction in simpliance with the "Corner Recordation and 170,22 IIII. a seq. M.D.A.)  Signature of Surveyor & Seal  Signature of Surveyor & Seal  Date 8=5 - Corner Record Signature Signat |
| SKETCH OF CORNER   | Employer Day't Si Stirve Ving Inc.   |
| ecord" was filed for record on the Aug 23  | Sec.   |
| ecord" was filed for record on the Qug 23  | day of 199/  |
| vas noted on the cross-index plat and is assigned page No.                       | 4500, in   |
| Corol M Quennings by But Bueloff   |  |