iment and accessories set to perpetuate the corner position

- Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking pography ties, position of accessories, etc.
- ertification must be signed and sealed by Registered Land Surveyor in State of Montan
- 6. Fill in Cross Index & Seciton Diagram at bottom of sheet.


## **CERTIFIED CORNER RECORDATION**

HES 503 COR 5 SEC ZI T31N R3IN LINCOLN CO.

FND OLD STONE MON W/"X" CUT 0.60' ABOVE GRD & "SHESSOS" WRITTEN ON SIDE FNO OLD BT IZ"LARCH NSO'E 76.73' DIST OLD BT SIGN READS: SEPBOIN ZTE T31N R31 SECZZ CORSHESSON POSTED BY 4915-S FNO OLD BT 8" LODGEPOLE PINE 544°E Z5.95' DIST OLD BT SIGN READS: N41º45'W ZSº POSTED BY 4975-S

SET STEEL POSTS W/ DECALS 52-4 1 52-9 NEST 1.2' DIST E) NORTH 1.Z' DIST.

FNO OLD STONE PILE 550°W 4.60' DIST



Cross Index No. HES. 503-5 T.37 R. 3/W PMM