

INSTRUCTIONS

1. Original and/or supplement record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

HES 503 COR1 SEC 22 T37N R31W LINCOLN CO.

FND OLD STONE MON W/ "X" CUT 1"± ABOVE GRD
 1"± HES 503 WRITTEN ON SIDE

FND OLD BT 12" LODGEPOLE PINE N01°W

6.60' DIST OLD SIGN READS: S3W 61°

T37N R31W SEC 22
 COR1 POSTED BY
 4975-S 10/90


FND OLD STONE PILE S57°W 6.70' DIST.

SET BT 9" LODGEPOLE PINE S62°W 15.64' DIST
 SCRIBED "X BT"

SET STEEL POSTS W/ DECALS 54-2 & 54-9

1) EAST 3.0' DIST

2) SOUTH 1.3' DIST



SKETCH OF CORNER

CERTIFICATION

I, _____
 certify the information shown herein is true and correct.

Signature Ground Party Chief

Thomas E. Sands

I, _____
 certify that this Corner Record correctly represents work performed
 by me or under my direction in compliance with the "Corner
 Recordation Act" (70-22-101, et seq., M.C.A.)

Signature of Surveyor & Seal

Date: 7/23/93 Reg. No. 7975-S


Employer: Sands Surveying, Inc.

Office of Clerk and Recorder, County of Lincoln. This "corner
 record" was filed for record on the July 27, 1993 day of 19,
 was noted on the cross-index plat and is assigned page No. 5364, in
 book No. _____

Coral M. Cummings By DB
 County Official

Cross Index No. HES 503-1 T 37N R 31W PMM

Sec.



• corner this sheet