

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

HES 484 COR 4 SEC 32 T 37N R 31N LINCOLN CO.

FND OLD STONE MON W / "X" CUT 0.60' ABOVE
GRD & "4 HES 484" WRITTEN ON SIDE

FND OLD BT 14" LODGEPOLE PINE (STANDING, DEAD)

N 45° W 13.67' DIST OLD SIGN READS: 4 HES 484
BEARING S 45° E

DID NOT REPLACE SIGN


SET BT 12" SPRUCE N 85° E 6.00' DIST SCRIBED "X BT"

SET BT 28" SPRUCE S 11° W 47.54' DIST SCRIBED
"4 HES 484"

SET STEEL POSTS W / DECALS 52-4 & 52-9

1) EAST 1.50' DIST

2) SOUTH 0.80' DIST



SKETCH OF CORNER

CERTIFICATION

I, _____
certify the information shown herein is true and correct.

Signature Ground Party Chief

Thomas E. Sands

I, _____
certify that this Corner Record correctly represents work performed
by me or under my direction in compliance with the "Corner
Recordation Act" (70-22-101, et seq., M.D.A.)

Signature of Surveyor & Seal

Date: 7/23/93 Reg. No. 7975-S


Employer: Sands Surveying, Inc.

Office of Clerk and Recorder, County of Lincoln. This "corner
record" was filed for record on the July 27, 1993 day of 19,
was noted on the cross-index plat and is assigned page No. 5380, in
book No. _____

Carol M. Cummings, DB
County Official

Cross Index No. HES 484-4 T. 37N R. 31W PMM

Sec.



• corner this sheet