

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

HES 481 COR 3 SEC 32 T 37N R 31W LINCOLN CO.

FND OLD STONE MON W/ "X" CUT 0.50' ABOVE GRD
 & "3HES 481" WRITTEN ON SIDE


FND OLD BT 30" LARCH STUMP 4' HIGH
 N 46° E 17.25' DIST

OLD SIGN READS: S 54° W 10' 4/28/61
 DID NOT OPEN BLAZE

SET BT 18" SPRUCE N 64° E 18.42' DIST
 SCRIBED "3HES 481"

SET BT 10" FIR S 87° W 12.61' DIST
 SCRIBED "X BT"

SET STEEL POSTS W/ DECALS 52-4 & 52-9
 1) S 16° W 1.0' DIST.



SKETCH OF CORNER

CERTIFICATION

I, _____
 certify the information shown herein is true and correct.

Signature Ground Party Chief

Thomas E. Sands

I, _____
 certify that this Corner Record correctly represents work performed
 by me or under my direction in compliance with the "Corner
 Recordation Act" (70-22-101, et seq., M.D.A.)

Signature of Surveyor & Seal

Date: 7/23/93 Reg. No. 7975-S


Employer: Sands Surveying, Inc.

Office of Clerk and Recorder, County of Lincoln. This "corner
 record" was filed for record on the July 27, 1993 day of 19,
 was noted on the cross-index plat and is assigned page No. 5385, in
 book No. _____

Coral M. Cummings
 County Official

Cross Index No. HES 481-3 T. 37N R. 31W PMM

Sec.



• corner this sheet