CERTIFICATE OF SURVEY

H.E.S. 113, Section 17,
Township 34 North, Range 34 West, P.M.M.
Lincoln County, Montana

PURPOSE: RETRACEMENT
The purpose of this survey is to retrace the exterior boundary of an existing parcel and is not a division of land. Section 76-3-404 MCA

FOR: MARK AND DELIA OWENS
OWNERS: MARK AND DELIA OWENS
DATE: July 2011

LEGEND

- ⊕ FOUND–CORNER MONUMENT AS NOTED
- ▲ FOUND–ORIGINAL STONE–H.E.S. #113
- ● FOUND–5/8" REBAR–PLASTIC CAP–11706 LS
- ⊗ SET–5/8"x 30" REBAR–3 1/4" DIA. ALUM. CAP–13582 LS
- ⊙ SET–5/8"x 30" REBAR–2" DIA. ALUM. CAP–13582 LS
- ○ COMPUTED POINT–NOT SET OR TIED
- POL POINT ON LINE
- X FENCE

BASIS OF BEARINGS

Bearings are based on Record of Survey, Book 7 of Surveys, Page 196, Instrument Number 251491, Records of Boundary County, Idaho, (Post 30 to Past 29 of the Montana/Idaho State Line as N00°12'04"E).

NOTE

1. Survey was completed July 15, 2011.

2. Corner #1 HES 113 is tilted to the NW. Corner #2 & CC HES 749 was used for alignment between the intersection with the State Line and Corner #2 HES 113.

3. The found original stone for Corner #5 HES 113 was remonumented with an aluminum cap and rebar. Reference CCR.

4. Small fenceline encroachments were noted between POL Cor. 1–Cor. 2 and the north end of the fence on the State Line.

5. N.R.C.S. Contract and Property Application #66–0211–10–006.

CERTIFICATE OF SURVEYOR

This is to certify that the survey was done by the undersigned, in accordance with the most recent minimum standards for boundary property surveys as set forth by the Montana Board of Professional Engineers and Land Surveyors. The accuracy and position tolerance also are in accordance with rural surveys.

[seal: MONTANA — STEVEN R. MOYER — 13582 LS — REGISTERED LAND SURVEYOR]

Steve R Moyer 8-9-11
REGISTRATION NUMBER 13582/LS

EXAMINED AUGUST 15 2011

Ronald A. Pearson
RONALD A. PEARSON
EXAMINING LAND SURVEYOR REG. NO. 9008 LS

STATE OF MONTANA
SS
COUNTY OF LINCOLN
FILED THIS 16th DAY OF Aug 2011
AT 10:30 P.M.
*Tammy D. Lauer*
CLERK AND RECORDER
BY *Jeannie Simms*
INSTRUMENT RECORD NUMBER 234216

CERTIFICATE OF SURVEY NO. 4699

Map Labels

H.E.S 750

H.E.S 113
28.99 AC.

Natural Resources Conservation Service
Wetlands Reserve Program Easement

H.E.S 749

Post No. 29, Mile 19.79 — Fnd.–Brass cap/iron post USGS
Post No. 30, Mile 20.40 — Fnd.–Brass cap/iron post USGS

IDAHO / MONTANA — State Line

Corner No. 5
Corner No. 4
Corner No. 3
Corner No. 2
Corner No. 1

See Detail 1
See Detail 2
See Detail 3

Latitude 48°42'33.68430"N
Longitude 116°02'56.60627"W (intersect point)

Boundary calls:
- S 64°13'41" W 902.71 (to int. pt.) / 467.49 / 435.22
- Cor. 4–Cor. 5 POL
- N 44°47'12" W 527.81 / 282.01 / 265.60
- POL Cor. 3–Cor. 4
- N 27°13'40" E 1155.50– / 441.98 / 445.18
- Cor. 2–Cor. 3 POL 2
- Cor. 2–Cor. 3 POL 1
- Cor. 2–Cor. 3
- 268.14
- N 65°10'18" E 727.98 (to int. pt.) / 401.72 / 326.26
- POL Cor. 1–Cor. 2
- POL Cor. 5–Cor. 1 (int. pt.–int. pt.)
- N 00°12'04" E 3198.22–
- 1315.27–
- 856.00
- 300.71
- 459.27
- 1582.24
- N end fence is 1.1 ft. East
- N–S fence is 0.4 ft. East
- fence corner is N26°E, 1.0 ft. fm int pt
- E end of fence is online

Detail 3 (not to scale)

IDAHO / MT.
H.E.S. 750
H.E.S. 113
Corner No. 5 & CC H.E.S.750
Corner No. 5 H.E.S. 113
N64°13'41"E 435.22 / 0.30 / 300.71 / 1315.27
See note
Intersect Point on State Line

Detail 1 (not to scale)

IDAHO / MT.
H.E.S. 113
H.E.S. 749
Corner No. 1 H.E.S. 113 (0.18 NW of cor.) See note
Corner No. 2 H.E.S. 749 & CC
N65°10'18"E 401.72 / 1315.27 / 1582.24
L1 / L2
Intersect point on State Line

Detail 2 (not to scale)

N 27°13'40" E 1155.50–
Cor. POL 2–Cor. 3
Found–plastic cap–5/8" rebar 11706 LS
S27°07'05"W, 113.40 fm POL 2 (0.22 SE of line)

LINE TABLE

L1 N65°10'18"E 1.33
L2 N55°13'36"E 1.05

BY: NORTH STAR SURVEYING, INC.
347 MOUNTAIN MEADOWS ROAD
NAPLES, IDAHO 83847
(208) 267-6209

SCALE: 1 INCH = 200 FEET
200 0 200 400

N *[compass rose]*