LINCOLN COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
AFFIDAVIT OF WASTEWATER TREATMENT AND DISPOSAL SYSTEM COMPLIANCE REVIEW FOR SYSTEM INSTALLED, REPAIRED OR REPLACED WITHOUT A VALID PERMIT

Issue Date: 02/023/2022

2023

Property Owner: Mossing, David

Mailing Address: [redacted]

Telephone: [redacted] (installer)

Name of Person Who Installed System Being Reviewed: Owner (inspected/confirmed by B. Persson)

Type of System Work Reviewed:

__XX__ New Installation ____ Existing System

____ Repair ____ Replacement ____ Extension ____ Other

Describe: 1,000-gallon septic tank. Gravity fed system with infiltrators (chambers). 3 laterals @ 100-feet in length each.

Property Description:

Legal: S12, T35 N, R26 W, C.O.S. PM 6645, ACRES 5.96, REMAINDER

Address or Location: 116 Kinklehorn Rd, Eureka, MT. 59917

Assessment Code: 0000014252

Reviewed Design Components:

Wastewater Flows: 300 gpd (3-bedroom) Sewer Lines: Schedule 40 PVS (4")

Septic Tank: 1,000 gallons Effluent Filter: Yes Dosing or Lift Tank: No

Drainfield: 300 Lineal Feet Drainfield Construction: infiltrators Hydraulic Function: yes

Comments: Installed by owner and inspected/confirmed by B. Persson. All supporting information/documentation provided by B. Persson.

System Review Documentation Statement:

I, Nicholas Raines, have inspected/reviewed the components of this system as listed above and found it to be in compliance with the sizing, construction, orientation and operating requirements of Chapter 17, Subchapter 36 A.R.M., Circular DEQ-4 and Lincoln County Wastewater Regulation.

Signed: Nicholas J. Raines *Date:* 02/23/2022


Title: *Environmental Health Specialist*

NOTICE: This document is not a permit for installation, repair or alterations of a wastewater treatment system. It is merely a statement of affirmation that the Department has conducted an on-site review of an otherwise illegal system and found it to be in compliance with all applicable requirements for that system. This affidavit effectively removes the illegal installation status on this system.

DISCLAIMER

This affidavit of review is not a guarantee by the Department that the system will continue to function properly for any prescribed period of time.

LOT LAYOUT


Water
3' bank
House
3- 100 ft. line
R 2 zone
1,000 gal tank
~ 15' from house
~ 28' from D Box
N