# CERTIFICATE OF SURVEY

## "BOUNDARY LINE ADJUSTMENT"

LOTS 47A-1 AND 47B-1, "WARLAND HEIGHTS SUBDIVISION", PLAT 6885RB NW1/4 SW1/4, SECTION 25, T.32N., R.29W., P.M., MT. FOR: JEAN M & DAVID E PITTSLEY DATE: JUNE, 2018

NATIONAL FOREST SYSTEM LANDS N89°24'35"E 346.89' (N89°21'25"E 348.03') N89°29'29"E 296.36' (N89°21'25"E 295.16') 75.00 TRUE POINT OF BEGINNING TRUE POINT PARCELS "C" & "47A-2" OF BEGINNING PLAT 6885RB, LOT 47B-1 PARCEL "47B-2" PLAT 6885RB, LOT 47A-1 "WARLAND HEIGHTS SUBDIVISION" WARLAND HEIGHTS SUBDIVISION" & Jean M & David E Pittsley LOT 47A-2 (Includes Parcel "C") 3.87 Acres LOT 47B-2 R=920.65' (920.65') Δ=1°42'52" (1°42'05") (Excludes Parcel "C") L=27.55' (27.34') R=920.65' (920.65')  $\Delta = 16^{\circ}26'48'' (16^{\circ}28'25'')$ L=264.27' (264.70') PARCEL 211.6 R=920.65' (920.65')  $\Delta = 9^{\circ}26'55" (9^{\circ}26'09")$ 19 L=151.82' (151.62') GASTON J MORIN R=226.11' (326.48') N78'23'55"W 273.18' [No BEARING 273.18']  $\Delta = 35^{\circ}03'04" (24^{\circ}05'25")$ R=343.73' {286.48'} Δ=27'18'29" {32'30'} L=138.32' (137.27') L=163.83' {162.50'} WARLAND HEIGHTS ROAD R=186.11' Δ=35'13'46" L=114.44' S89°35'34"W 427.06' (S89°30'27"W 427.15') PLAT 1, LOT 46 MONTANA STATE Gary H. Vanaken HIGHWAY No. 37

LEGEND

- ♠ A 5/8 INCH DIAMETER REBAR MARKED KED 4975S
- A 5/8 INCH DIAMETER STEEL REBAR WITH 3 1/4 INCH ALUMINUM CAP MARKED BOYER, 9750LS
- SET A 5/8 INCH DIAMETER REBAR WITH PLASTIC CAP MARKED HUGHES, 7322LS
- O AN UNMARKED COMPUTED POINT

} PLAT 2009 RE	ORD ( ) PLAT	6885RB RECOR	[ ] cos	No. 3028 RECORD
----------------	--------------	--------------	---------	-----------------

BOUNDARY LINES — — OLD BOUNDARY LINE

EXISTING ROAD EDGE

ADJOINING BOUNDARIES RIGHT OF WAY CENTERLINE

---- RIGHT OF WAY LIMITS

RIGHT OF WAY CURVE RADIAL

### BASIS OF BEARING

The basis of bearing for this survey is S00°48'10"W, derived from Survey Grade GPS system calibrated to local control between between C-N-SW 1/64, Section 25, and the SW 1/16 corner section 25, both being 2 1/2 inch diameter aluminum pipe with 3 1/4 inch aluminum cap marked BOYER, 9750LS

> VICINITY DIAGRAM SW 1/4, SECTION 25

#### METHOD OF SURVEY

RTK radial procedures to tie previously set controlling corners by Levi Powell, May 2018

□ LOT GAINING ACRES □ LOT LOSING ACRES

### LEGAL DESCRIPTION; PARCEL "C"

An irregular parcel of land, lying northeasterly from Libby, Montana, Lincoln County, within the NW1/4 SW1/4, Section 25, T.32N., R.29W., P.M.,MT., within Lot 47B-1, "Warland Heights Subdivision", Plat 6885RB and more particularly described as follows: Commencing at the Center North of Southwest sixty fourth Corner (C-N-SW 1/64) said Section, a 5/8 inch diameter steel rebar with 3 1/4 inch aluminum cap marked BOYER, 9750LS; Thence S89°24'35"W 271.89 feet to a set 5/8 inch diameter rebar with plastic cap marked HUGHES, 7322LS and the TRUE POINT OF BEGINNING;

Thence along "New Boundary" S00°26'45"W, 522.66 feet to northerly Right of Way Limits of "Warland Heights Road" being 40 feet from Centerline, a set 5/8 inch diameter rebar with plastic cap marked HUGHES, 7322LS; Thence along said Limits N78°23'55"W, 76.44 feet to a 5/8 inch diameter rebar marked KED 4975S; Thence along "Old Boundary" between Lots 47A-1 and 47B-1, Plat 6885RB N00°26'45"E, 211.67 feet to a 5/8 inch diameter rebar marked KED 4975S; Thence along said boundary N00°26'45"E, 294.85 feet to a 5/8 inch diameter rebar marked KED 4975S; Thence along west-east subdivision line, said Section N89°24'35"E, 75.01 feet to the TRUE POINT OF BEGINNING, containing 0.89 acres. Subject to and together with all appurtenant easements of record.

LEGAL DESCRIPTION; LOT 47A-2


An irregular parcel of land, lying northeasterly from Libby, Montana, Lincoln County, within the NW1/4 SW1/4, Section 25, T.32N., R.29W., P.M., MT., within Lots 47A-1 and 47B-1, "Warland Heights Subdivision", Plat 6885RB and more particularly described as follows: Commencing at the Center North of Southwest sixty fourth Corner (C-N-SW 1/64) said Section, a 5/8 inch diameter steel rebar with 3 1/4 inch aluminum cap marked BOYER, 9750LS: Thence S89°2435"W 271.89 feet to a set 5/8 inch diameter rebar with plastic cap marked HUGHES, 7322LS and the TRUE POINT OF BEGINNING;

Thence along "New Boundary" S00°26'45"W, 522.66 feet to northerly Right of Way Limits of "Warland Heights Road" being 40 feet from Centerline, a set 5/8 inch diameter rebar with plastic cap marked HUGHES, 7322LS; Thence along said Limits N78°23'55"W, 76.44 feet to a 5/8 inch diameter rebar marked KED 4975S; Thence along said Right of Way Limits through a curve left: Radius 226.11 feet, Delta 35°03'04", arc length 138.32 feet to a 5/8 inch diameter rebar marked KED 4975S; Thence along easterly Right of Way Limits of "Montana State Highway No. 37" being 130 feet from Centerline through a curve left: Radius 920.65 feet, Delta 16°26'48", arc length 264.27 feet to a 5/8 inch diameter rebar marked KED 4975S; Thence along said curve through a Radius: 920.65 feet, Delta 1'42'52", arc Length 27.55 feet to a 5/8 inch diameter rebar marked KED 4975S; Thence along Boundary between Lots 43 and 47, Plat No. 1 N00°16'48"E, 274.39 feet to a 5/8 inch diameter rebar marked KED 4975S; Thence along west-east said Section Subdivision line N89°29'29"E, 296.36 feet to a 5/8 inch diameter rebar marked KED 4975S; Thence along said line N89°24'35"E, 75.01 feet to the TRUE POINT OF BEGINNING, containing 3.87 acres. Subject to and together with all appurtenant easements of record.

LEGAL DESCRIPTION; LOT 47B-2

An irregular parcel of land, lying northeasterly from Libby, Montana, Lincoln County, within the NW1/4 SW1/4, Section 25, T.32N., R.29W., P.M., MT., within Lot 47B-1, "Warland Heights Subdivision", Plat 6885RB and more particularly described as follows: Commencing at the Center North, Southwest sixty fourth Corner (C-N-SW 1/64) said Section, a 5/8 inch diameter steel rebar with 3 1/4 inch aluminum cap marked BOYER, 9750LS and the TRUE POINT OF BEGINNING:

Thence along boundary between Los 47 and 48, Plat No. 1 S00°48'10"W, 664.52 feet to Southwest sixteenth Corner, said Section, a 5/8 inch diameter steel rebar with 3 1/4 inch aluminum cap marked BOYER, 9750LS; Thence along east-west Section Subdivision Line S89°35'34"W, 427.06 feet to easterly Right, "Montana State Highway No. 37" being 130 feet from Centerline, an uncapped 5/8 inch diameter rebar; Thence along, said limits through Curve left: Radius 920.65 feet, Delta 9°26'55", Arc Length 151.82 feet, a 5/8 inch diameter rebar marked KED 4975S; Thence along Northerly Right of Way Limits of "Warland Heights Road" being 40 feet from Centerline through curve right: Radius 226.11 feet, Delta 35'03'04", Arc Length 138.32 feet, a 5/8 inch diameter rebar marked KED 4975S; Thence along said Limits S78°23'55"E, 76.44 feet to a set 5/8 inch diameter rebar with plastic cap marked HUGHES, 7322LS; Thence along "New Boundary" between Lots 47A-2 and 47B-2 N00°26'45"E, 522.66 feet to a set 5/8 inch diameter rebar with plastic cap marked HUGHES, 7322LS; Thence along west-east Section Subdivision Line N89°24'35"E, 271.89 feet the TRUE POINT OF BEGINNING, containing 4.77 acres. Subject to and together with all appurtenant easements of record.



PURPOSE OF SURVEY AND OWNER'S EXEMPTION CERTIFICATION We, Jean M. and David E. Pittsley, and Arthur D. Bettge being the record owners, hereby certify We further certify that Parcel "C" being added to lot 47A-2 is exempt from sanitation review by the Department of Environmental Quality pursuant to ARM 17.36.605(2)(a) as a parcel that has no existing facilities for water supply, wastewater disposal, or solid waste disposal, if no new facilities will be constructed on the additional parcel. Furthermore: Lot 47B-2 is exempt from sanitation review by the Department of Environmental Quality pursuant to ARM 17.36.605(2)(b)(i)(ii) as a parcel that has no existing facilities for water supply, wastewater disposal, or solid waste disposal other than those that were previously approved by the reviewing authority under Title 76, chapter 4, part 1, M..C.A. or that were exempt from such review because no new facilities will be constructed on the parcel and the division of land will not cause approved facilities to violate and conditions of approval, and will not cause exempt facilities to violate and condition of exemption.

ACKNOWLEDGMENT

The foregoing Exemptions were subscribed and acknowledged before me a Notary Public for County of Lincoln by JEAN M. AND DAVID E. PITTSLEY

ACKNOWLEDGMENT

ARTHUR D. BETTGE

201 . In witness whereof, air Brows

NOTARY STATE OF

ONAL LAND

HISTORY OF SURVEYS

1913 - Plat No. 1, "Warland Heights Subdivision"
1972 - Plat No. 2009, Right-of-Way, Warland Heights Road
1981 - COS No. 934, Section 25 breakdown, Melvin D. Lauteren, 4232S
2001 - COS No. 3028, Retrace adjoining Lot 48, Steven A. Boyer, 9750LS

2004 - Amended Plat No. 6563, Lot 47, "Warland Heights Subdivision", Kenneth E. Davis, 4975S 2008 - Plat No. 6885RB, Lot 47A-1, "Warland Heights Subdivision", Kenneth E. Davis, 4975S

LAND SURVEYOR'S CERTIFICATION

I hereby certify that I am a Registered Land Surveyor in the State of Montana, that the survey shown on this "Certificate of Survey" has been prepared under my supervision and in accordance with the Montana Code Annotated, Sections 76-3-101 through 76-3-625, and the Lincoln County Regulations adopted pursuant thereto.

EXAMINING LAND SURVEYOR'S CERTIFICATION

Ronald A. Pearson, PLS 9008LS, Lincoln County Examining Land Surveyor

COUNTY TREASURER'S CERTIFICATION

CLERK AND RECORDER'S CERTIFICATION

CERTIFICATE OF SURVEY No.