INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.
Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated.

3. Description of monument and accessories set to perpetuate the corner position.

Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography lies, position of accessories, etc.

Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
Fill in Cross Index & Seciton Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION


Co	orner	CE_1/16	Sec.	 26N	R.	29W	P.M.M.	Lincoln	0	County

Set 5/8" X 24" capped steel pin stamped JHN 4661S

Set 12" Larch bearing tree scribed CE 1/16 BT from which the corner bears S 07 W

Set 6" Larch bearing tree scribed CE 1/16 * Sec. 22 from which the corner bears N 80 E

Set a location poster on a 14" Ponderosa Pine from which the corner bears S $44^{\circ}E$ 7.8 ft.



Janes BF Siegel by Betty County Official

deputiz

· - corner this sheet

T. 26N R 29W PMM

book No. .