## INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- corners.
  3. Description of monument and accessories set to perpetuate the corner position.
  4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
  5. Certification must be signed and scaled by Land Surveyor registered in the State of Montana.
  6. Fill in Cross Index & Section Diagram at bottom of sheet.

Corner CN /// <sub>1/0</sub>	Sec. 27	T. 27 N	R. <u>28 W</u>	P.M.M. LINCOLN	County
ORIGINAL AND/OR SUBSEQUENT RECORD	None				

EVIDENCE FOUND

None

PERPETUATION

Set 11/2" Alum. Cap on 5/8"x 24" Rebar. Established Two RM Trees An 10" D.Fir 5220W, 1.8 Feet. An 8" D.Fir bears 5360E, 8.7 Feet.

Note: Declination used - 20°E Measurements taken to center of tree

