INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.

Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

Description of monument and accessories set to perpetuate the corner position.
Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.


Certification must be signed and scaled by Registered Land Surveyor in State of Montana.
Fill in Cross Index & Seciton Diagram at bottom of sheet.

#62-82-5

CERTIFIED CORNER RECORDATION

T. 30N <u>SE 1-16</u> Section 28 26W Lincoln County

- I. No original record.
- At the corner position, set a $2\frac{1}{2}$ x 30 inch pipe with a 3 inch II. aluminum cap marked as shown below, raised 3 ft. dia. mound of stones around the pipe, from which the following accessories: A fir, 12 inches dia., bears S63°W, 25.4 ft. dist. marked SE 1-16 BT. A tamarack, 9 ins. dia. bears N6°W, 30.7 ft. dist. marked SE 1-16 BT. Painted all blazes red, placed sign on BT's, set a fiberglass post alongside the monument and placed a location poster and survey monument sign on a nearby tree



Office of Clerk and Recorder, County of This "corner	Sec. 28
was noted on the cross-index plat and is assigned page No. $\frac{3337}{2}$, in	
book No Janet BF Siegel by Betty L. Conces	├ ─ ├ ─ ├
County Official Seperty	
Cross Index No. U-12 T. 30N R. 26W PMM	• - corner this sheet