

CERTIFIED LAND CORNER RECORDATION

Cadastral Retracement $\frac{1}{4}$ cor. sec. 6/5 T30N R30W Montana Principal Meridian
DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

T30N R30W Montana Principal Meridian G.L.O. notes book 3420 page 42 gives the original notes for the setting ~~TM~~ of the $\frac{1}{4}$ cor. of 6/5 T30N R30W. Notes indicate a limestone 14x9x9 9" in the ground. Found a BLM brass cap marked: T30N R30W

S6 $\frac{1}{4}$ S5
1964

Record: 18" tamarack bearing S33° E 24 lks., marked $\frac{1}{4}$ S5 BT
Found: Bearing tree alive and still growing and presently 22" in diameter and the blaze is overgrown

Found: 8" fir bearing S42° W, 9 lks., with overgrown blaze

No record.....

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


Date of work: 4/18/74

No added monumentation

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.
(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

Sketch on reverse side

Surveyor's Seal



I, James R. Staples
certify that the information shown herein is true and correct.

James R. Staples
Signature of Ground Party Chief

I, JOHN C. ERICKSON
certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

John C. Erickson
Signature of Surveyor

3979 S
Registration Number

DIAGRAM OF CORNER:

T30N R30W
N. $\frac{1}{4}$
6 * 5

= Corner recorded on the sheet


Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 28 day of Mar 1989, was noted on the cross-index plat and is assigned page No. 3983, in book No.

Janet BF Sugil by Bill Schloff
County Official

6

8" FIR BEING S42°W,
9 LKS., WITH OVERGROWN
BLAZE



BLM BRASS CAP MARKED:
T30N R30W

1/4
S6 / S5
1964

5

22" TAMARACK
BEARING S33°E, 24 LKS.
WITH OVERGROWN BLAZE

