
INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corn	ner T T	R.	P.N	M.M.	County
I. 1	No record found at Lincoln County Courthouse				

- No evidence on the ground.
- III. At the determined corner position by survey, set a 3/4 ins. dia. aluminum rod, 30 ins. long, 27 ins. in the ground with attached 3 1/4 ins. dia. U.S.D.A. Forest Service aluminum cap marked as shown:



from which

A fir, 18 ins. dia., bears S70 $^{\circ}$ E, 4.6 ft. dist., mkd. NW-SW 1/64 S 1 BT. A fir, 9 ins. dia., bears N24 $^{\circ}$ W, 14.8 ft. dist., mkd. X BT.


Painted a red band around each bearing tree and attached "Land Survey Monument" and "Bearing Tree"

Magnetic Declination: East, 20

record" was filed for record on _

book No. _

was noted on the cross-index plat and is assigned page No



Cross Index No.

C .5-21.5

County Official✓

30 N

corner this sheet