nord used to evaluate the corner position.

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterate


Description of monument and accessories set to perpetuate the corner position

- Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

CERTIFIED CORNER RECORDATION

Corner Northwest Corner Section 1 _ P.M.M. __ County

- 1. 80 Chains: Set a Limestone 18 X 9 X 4 inch 12 inches in the ground, for corner of Sections 12,35 and 36 marked with 1 notch on East and 5 notches on West edges, from which, a Pine 16 inches diameter bears N76 30'E 87 links distance marked T32N.,R.29W S36 BT. A Pine 20 inches diameter bears S66 20'E 78 links distance marked T31N.,R.29W S1 BT. A Pine 24" diameter bears S57 20'W 47 links distance marked T31N.,29W S2BT. A Pine 24 inches diameter bears N32 50'W 69 links distance marked T32N.,R.29W S35 BT.
- 2. Found: B.L.M. brass capped monument (marked as shown below) from which a Pine 18" diameter bears N24½°E 25.7 feet. An 8" Fir snag bears S76°30'W 27.1 feet and an 8" Pine bears N55°15'W 44.2 feet all are scribed and posted by ART 1972.



Found B.L.M. Brass capped monument marked as shown.

